


381/369+

JC903 U.S. PTO  
09/966176  
09/28/01

Fig. 1

1/9



0966176-00026

381/369  
L.S.

2/9

Fig. 2




Fig. 3






Fig. 4

3/9




4/9



+

5/9

Fig. 7



+

**Fig. 8**

80

82 84 86 88 90 92 94 96 98

MSI RSI MCFLEX RCFLEX CD RD MD

CONVERSION

INVERSE CONVERSION

RCOMP LCOMP C CV

C CIRCUIT

C CARTRIDGE

108 106 104

V1

[illegible]

7/9

Fig. 10




Fig. 11






Fig. 12



8/9

*Fig. 13*



0996176.002601



*Fig. 14*

